



1, the 10.1inch LCD is with TTL interface

2, the driver board has two interfaces, TTL and LVDS

3, the driver board you get has LVDS function, not TTL function,

so the board can not drive the 10.1inch LCD

4, let us send you a TTL to LVDS adapter with a cable in next package, so the problem would be solved.

5, in future order for RPIA0091, the driver is TTL function, no change for item RPIA0091.



